

0.4.5.

*East Fork  
Mojave R.*

**EAST FORK OF VIRGIN RIVER RIVER DISTRIBUTION SYSTEM**  
Inventory of Water Measuring Devices and Diversion Structures on the River System.

Water User: Name and Address	Ditch or Canal	Present Diversion Structure	Diversion Facilities Recommended	Present Measuring Device	Measuring Facilities Recommended	Special Remarks
Heaton Ranch Grant Heaton Moccasin, Arizona	Power ditch	none	screw type headgate	none	3-in. Parshall flume	Power plant not in operation, locked gate, commissioner requires key (Dairy Canyon)
	Ditch above Power ditch Upper ditch	"	"	"	"	right in question (Dairy Canyon)
	Ditch below	"	"	"	"	right in question
	Power ditch Lower Ditch, along side road	"	"	"	"	(Dairy Canyon) right in question
Whit McDonald Merrill McDonald Kanab, Utah	Leone Ditch Reservoir ditch ditch by road field ditch	" outlet structure none none	" none screw upper headgate "	" " " "	" Parshall flume 3-in. Parshall flume "	carries storage water
Major's Ranch Duke Aiken Kanab, Utah	old ditch pasture dam	" canvas dam	" "	" "	" "	ditch not used for some time

*Award No*  
C 35

**EAST FORK OF VIRGIN RIVER RIVER DISTRIBUTION SYSTEM**  
Inventory of Water Measuring Devices and Diversion Structures on the River System.

Water User: Name and Address	Ditch or Canal	Present Diversion Structure	Diversion Facilities Recommended	Present Measuring Device	Measuring Facilities Recommended	Special Remarks
Duncan McDonald P. O. Box 213 Kanab, Utah	Upper pasture ditch Middle Pasture Ditch Lower Pasture Ditch	none " "	Screw Type Headgate " "	none	3-in. Parshall flume " "	
Howard Spencer Glendale, Utah	Jump-up Ditch other ditches	none "	Screw type headgate "	none		evaluate after completion of highway
Henry Carroll Orderville, Utah	Canyon Ditch	"	"	25-in. Parshall flume	replace	Flume odd size, needs to be re- placed.
Lyle Chamberlain Glendale, Utah	Flume ditch	"	"	none	Parshall flume	
John W. Hopkins Carpenter Ranch Lessee, C. W. Brinkerhoff Glendale, Utah	Canyon Ditch					

**EAST FORK OF VIRGIN RIVER**  
**RIVER DISTRIBUTION SYSTEM**  
 Inventory of Water Measuring Devices and Diversion Structures on the River System.

Water User: Name and Address	Ditch or Canal	Present Diversion Structure	Diversion Facilities Recommended	Present Measuring Device	Measuring Facilities Recommended	Special Remarks
<b>Lessee:</b> C. W. Brinkerhoff Glendale, Utah						
Glendale Irrigation Co. c/o Charles C. Anderson Glendale, Utah	East Ditch West Ditch	Brush Diversion Dam Wood headgate "	See Remarks "	2-ft. concrete Parshall Flume "	none "	Diversion poor, extremely difficult, recommend installa- tion of good diver- sion dam with screw type headgate.
Orderville Irrigation Co. c/o Mark Chamberlain Orderville, Utah	Orderville Ditch	Cement & Rubble structure, screws	none <del>Screw-type headgate</del>	2-ft. concrete Flume	"	
Mt. Carmel Irrigation Co. c/o Sharon Lamb Orderville, Utah	Westside Ditch	Track & Rock diver- sion dam with screw type headgate	none	"	reset or replace	submerged
<u>1</u> As to any ditch where right is in question, no installation as diversion of water should be made until the right is established.	Eastside Ditch			"	none	